

Spectrum Info Solutions

26, Sylvester House-B,
D'Souza Wadi,
Thane (W) 400 604

INSTALLATION REPORT

Customer Name & Address

HDFC Bank
Wilson Tower,
Kandivali (W),
Mumbai 400 105
Tel No. 28362541

Invoice No : 5547
Date : 07-Nov-2011
Model Name : LWA5AR5A
SI No : 55854544444
Compressor No :
Date of Installation : 14-Nov-2011
Card No. : 5

Details of Installation -

	Home	Office
Location	<input type="checkbox"/> Bedroom <input type="checkbox"/> Living Room <input type="checkbox"/> Any Other	<input type="checkbox"/> Cabin <input type="checkbox"/> Open Office <input type="checkbox"/> Machine or Computer Room <input type="checkbox"/> Conference or Meeting Room

Installation Details

Sheet Metal Parts OK / Not OK
Compressor OK / Not OK

Supply Voltage Details

AC Voltage
Stabilizer Rating & Type
Earthing Proper / Not Proper
Circuit Breaker Used / Not used

Performance Check

Compressor Start Up OK / Not OK
Fan Motor OK / Not OK
Swing Operation OK / Not OK
Cooling OK / Not OK
Temperature Reading OK / Not OK
Starting Current AMPS
Running Current AMPS
Liquid Pressure
Suction Pressure

Unit has been installed and working to my satisfaction. I have also been explained about its operation & normal care of the machine.

Customer's Signature

Service Engineer

Spectrum Info Solutions

26, Sylvester House-B,
D'Souza Wadi,
Thane (W) 400 604

INSTALLATION REPORT

Customer Name & Address

HDFC Bank
Wilson Tower,
Kandivali (W),
Mumbai 400 105
Tel No. 28362541

Invoice No : 5547
Date : 07-Nov-2011
Model Name : LWA5AR5A
SI No : 96855544477
Compressor No :
Date of Installation : 14-Nov-2011
Card No. : 6

Details of Installation -

Home

Office

Location

- Bedroom
 Living Room
 Any Other

- Cabin
 Open Office
 Machine or Computer Room
 Conference or Meeting Room

Installation Details

Sheet Metal Parts OK / Not OK
Compressor OK / Not OK

Supply Voltage Details

AC Voltage
Stabilizer Rating & Type
Earthing Proper / Not Proper
Circuit Breaker Used / Not used

Performance Check

Compressor Start Up OK / Not OK
Fan Motor OK / Not OK
Swing Operation OK / Not OK
Cooling OK / Not OK
Temperature Reading OK / Not OK
Starting Current AMPS
Running Current AMPS
Liquid Pressure
Suction Pressure

Unit has been installed and working to my satisfaction. I have also been explained about its operation & normal care of the machine.

Customer's Signature

Service Engineer

Spectrum Info Solutions

26, Sylvester House-B,
D'Souza Wadi,
Thane (W) 400 604
